

Wireless Measurement Read WiMER2 User Guide

Important Notes

- Turn off the device after use. It will **NOT** turn off automatically.
- Do NOT open the device. Opening causes permanent damage and voids the warranty.

Description

- 1 10-Pin Connector connects to data cable
- 2 Tri-Color LED
 - Device is on
 - Oevice is in charge
 - Device is fully charged
- 3 **USB Port** connects to USB cable to charge
- 4 On/Off Button push on and push off
- 5 **Trigger Connector** 2.5 mm audio port, connects to trigger switch



Included in the box

- WiMER2 Base 1X
- Trigger Switch 1X
- USB Charging Cable 1X
- USB Power Adapter 1X
- User Guide 1X

Compatible Software

- iOS: MultiGage Reader
- Android: MultiGage Reader
- Windows: MultiGage Reader (BLE Dongle Required)
- iOS app can be directly downloaded from the App Store for FREE.
- Android app can be directly downloaded from the Google Play Store for FREE.
- Windows software is available on Motionics website.

Quick Start

- Turn on WiMER2 and connect to Fowler Test Indicator.
- Plug in USB Bluetooth dongle if using Windows PC.
- Run one of the aforementioned Apps/software.
- In the main page, tap Pair button to bring up a new pairing page.
- Wait for the software to finish scanning nearby devices, select WIMERXXX to connect.
- Connection may take a few seconds, once paired, instrument reading shows in the software.

Motionics, LLC www.motionics.com 8500 Shoal Creek Blvd Building 4 Suite 209, Austin, TX, 78757 © 2020 Motionics, LLC. All rights reserved. info@motionics.com

Made in the U.S.A